




C0153 9-5
08B/0520

0520 Otro equipo interior - Otro equipo interior (1998 - 2002)

Pos	Pieza N°.	Artículo	Utilización	Ctd
1	50 96 235	Asidero Note: Ch. W3073927--		4
1	50 96 235	Asidero Note: Ch. X3000883--	LHD, CA, US	4
2	79 77 002	Tornillo	1998-2001	8
3	50 98 801	Visera	LH, NLS-USE 5132808	1
3	50 98 819	Visera	RH, NLS-USE 5132816	1
4	79 22 370	•Tornillo		3
5	46 83 165	•Soporte		1
6	51 32 808	Visera Note: Ch. X3028921--	1999-2001, LH	1
6	51 32 816	Visera Note: Ch. X3028921--	1999-2001, RH	1
6	43 69 062	Visera	1998-2001, LHD, US, LH	1
6	43 69 047	Visera	1998-2001, LHD, US, RH	1
6	43 69 500	Visera	1998-2001, LHD, CA, LH	1
6	43 69 518	Visera	1998-2001, LHD, CA, RH	1
7		•Etiqueta	LHD, CA, US Ir a 8D - 160	1
8	46 03 411	•Soporte	1998-2001	1
8A	79 22 370	••Tornillo		1
9		•Bombilla	Ir a 3A - 370	1
10	79 22 370	•Tornillo		2
11	49 03 811	Retrovisor Note: Ch. X3038473--		1
12	79 75 329	•Tornillo		3
13		Cubierta	Ir a 3A - 370	
14	50 00 245	Retrovisor Note: Antideslumbramiento automático	1998-2000	1
15	50 86 152	•Botón de presión		1
16	79 86 367	•Tornillo		3